

How to
Measure

SPLINT

BOOTS XP#1032

Measure circumference
at splint bone

Small 7½" to 8½"

Medium 8½" to 9½"

Large 9½" to 10½"

